



# Invoice

Date	Invoice #
4/21/2020	10207

4211 Gilman Ave W  
 Seattle, WA 98199  
 206 542 5466

**PAID**  
**04/21/2020**

Billing/Owner	206-550-4259
Scott Krzyzanowski 8830 40th Ave SW Seattle, WA 98136	
Contact/Site	
Scott Krzyzanowski 8830 40th Ave SW Seattle, WA 98136	

Description	Amount
Video Inspection	200.00T
Sewer Scope/ Inspection Legality- Sewer Inspections cannot be guaranteed. What we interpret today is what we see at this time. Things in the sewer line can change due to many reasons. Sewer Inspections do not guarantee any issues or problems that may arise in the future. -Accessed line through 4" cleanout in basement bathroom 4" concrete pipe at 7' with moderate to heavy erosion -6" Concrete pipe at 79' with moderate erosion -Maximum run of 100', camera travel stopped by small piece of debris in line -Line appears to be open and flowing at this time -No repairs required up to 100' Tech- Parnell Credit Card Surcharge 2.75%	6.06T

All credit card transactions  
 will be charged a 2.75%  
 surcharge fee.

<b>Subtotal</b>	\$206.06
<b>Sales Tax</b>	\$20.81
<b>Payments</b>	-\$226.87
<b>Total</b>	\$0.00

TERMS: PAYMENT UPON COMPLETION UNLESS PREAUTHORIZED. NET 30 ON EXISTING ACCOUNTS WITH AGREEMENT TO PAY ALL COSTS OF COLLECTION IN THE EVENT OF DEFAULT, INCLUDING INTEREST COMPUTED AT THE RATE OF 1 1/2% PER MONTH.

WARRANTY: MATERIALS BY MANUFACTURERS WRITTEN WARRANTY ONLY. WORKMANSHIP 2 YEARS UNLESS OTHERWISE STATED IN WRITING.

SIGNATURE: \_\_\_\_\_ DATE: \_\_\_\_\_